

# SUPPLEMENT SHEET

FORM No 43970 (6'86)  
DATE June 9, 1986  
SUBJECT 42" Snow Blade  
Attachment, Model No LC010BR  
(insert between pages 4 and 5)

## OWNERS MANUAL SUPPLEMENT 42" SNOW BLADE ATTACHMENT MODEL LC 010BR

(Insert between pages 4 & 5)

There was a design change in lift shaft assembly on certain Roper models. Due to this change, it will be necessary to use a different lift arm assembly on Roper models LT110CR, YT160CR, YT140AR and YTH160AR. The new lift arm needed for the newer models is Part Number 23433. Older production models, LT110AR-BR and YT160AR BR, will require lift arm, Part Number 23217. Both lift arms are included in the loose parts kit (See illustration)

Use on LT110AR & BR  
YT160AR & BR



Part Number 23217

Use on LT110CR, YT140AR  
YTH160AR & YT160CR



Part Number 23433

**ROPER**

**OUTDOOR POWER PRODUCTS**

DIVISION OF ROPER CORPORATION

Ref #	Part Number	Qty	Description
1	23118		BLADE HEAD
2	43080		BOLT
3	43079		BOLT
4	43079		BOLT
4	43064		NUT
5	43081		WASHER
6	23070		SHOE, SKID
7	23117		WEAR STRIP
8	62142		PLATE
9	43010		COTTER PIN
10	62143		PIVOT PLATE ASSY
11	62167		CHANNEL ASSY
12	23128		LIFT HANDLE ASSY
13	43362		HANDLE GRIP
14	43062		BOLT
15	73003		
16	43082		LOCKNUT
17	43020		BOLT
18	43262		NUT
19	23151		BAR ANGLE LO
20	23129		BAR
21	43350		BOLT
22	43349		ROLL PIN
23	23131		BOLT
24	23130		BRACKET
25	43348		SPRING
26	43263		SPRING
27	43264		BOLT
28	43083		NUT
29	43331		CAP
	43776		OWNER'S MANUAL