

Brand | Flymo


date | 25/02/04

**SUBJECT: Hedgetrimmer Spare**

<b>Products Affected:</b>	<b>HT 42</b>	<b>9648147-01</b>
	<b>HT420</b>	<b>9648143-01</b>
	<b>HT450</b>	<b>9648144-01</b>
	<b>HT600</b>	<b>9648153-01</b>
	<b>HT510</b>	<b>9648159-01</b>




**Only the spares listed below are available for these products.  
If any other repairs are necessary contact the warranty department for  
exchange authorisation.**



Safety Guard

Product



Bladesheath

Spares Available



Bladeset - Gear Housing

HT42	Safety Guard	5128242-02
	Bladesheath	5131196-01
HT420	Bladeset - Gear Housing	5128241-01
	Safety Guard	5128242-01
HT450	Bladesheath	5131196-01
	Bladeset - Gear Housing	5128241-01
HT510 / 600	Safety Guard	5128242-01
	Bladesheath	5131196-01
	Bladeset - Gear Housing	5128241-02
	Safety Guard	5128242-01
	Bladesheath	5131196-02
	Bladeset - Gear Housing	5128241-03